ASS V 3.1.01 Ground level foot.



Scale 1/4

All dimensions are indicative unless specified on the drawing
Sheet thickness may be exaggerated for clarity

Notes:

- 'A' shows foot of seam finished according to ASS V 1.2.1.01a.
- 'B' shows foot of seam finished according to ASS V 1.2.1.01b.
- In absence of local or national regulations, a gap of 150mm is recommended between the ground and the bottom edge of the cladding.
- Generic structural details are given for indicative purposes only.

1. elZinc® cladding
2. Membrane
3. Structural underlay
4. Folded galvanised steel profiles
5. elZinc® perforated sheet
6. elZinc® retention profile
7. Insulation
8. Wooden batten
9. Wall bracket
10. Substrate

elZinc®
Tel. +34 984 116 332
Fax. +34 985 493 202
www.elzinc.es
Asturiana de Laminados S.A.
Pol. Ind. de Olloniego, Parcela C1
33660 Olloniego Asturias, Spain
elzinc@aslazinc.com

ASS V 3.1.01 Ground level foot.



Scale 1/4

All dimensions are indicative unless specified on the drawing
Sheet thickness may be exaggerated for clarity

Notes:

- 'A' shows foot of seam finished according to ASS V 1.2.1.01a.
- 'B' shows foot of seam finished according to ASS V 1.2.1.01b.
- In absence of local or national regulations, a gap of 150mm is recommended between the ground and the bottom edge of the cladding.
- Generic structural details are given for indicative purposes only.

1. elZinc® cladding
2. Membrane
3. Structural underlay
4. Folded galvanised steel profiles
5. elZinc® perforated sheet
6. elZinc® retention profile
7. Insulation
8. Wooden batten
9. Wall bracket
10. Substrate

elZinc®
Tel. +34 984 116 332
Fax. +34 985 493 202
www.elzinc.es

Asturiana de Laminados S.A.
Pol. Ind. de Olloniego, Parcela C1
33660 Olloniego Asturias, Spain
elzinc@aslazinc.com