
Traditional systems - Double lock standing seam

01

DLSS FG 7.2.01 Vally gutter .



All dimensions are indicative unless specified on the drawing Sheet thickness may be exaggerated for clarity

## Scale 1/5

## Notes:

For roofs pitched at 10° and above on both sides of valley.

- 1. elZinc® cladding Protect+
- 2. Roofing membrane
- 3. Structural underlay
- 4. Folded galvanised steel profiles
- 5. elZinc® perforated sheet
- 6. elZinc® retention profile
- 7. Celular glass insulation
- 8. elZinc® hung gutter
- 9. Gutter clip
- 10. Gutter bracket
- 11. elZinc® clip
- 12. Hot applied bitumen13. Separating membrane
- 14. Fixing plate in galvanised

Sistema de Gestión de Calidad Certificado nº 12 100 42 851 TMS

The information contained in this document-drawing- has a purely informative function and been elaborated with the intention of assisting building professionals in regard to the installation of elZinc® cladding systems. It is the responsability of the architect, building contractor and installer in any case to ensure the validity of the specific details employed on each project. Asla-elZinc® rejects any responsibility due to direct or indirect damage that may arise from the use of the information contained in this document



elZinc® Tel. +34 985 676 000 Fax. +34 985 692 000 www.elzinc.es